From: Wagner, Christine [/O=EXCHANGELABS/OU=EXCHANGE ADMINISTRATIVE GROUP

(FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=12068C1889924ECF96F692831F0C77D4-CWAGNE02]

**Sent**: 2/4/2020 9:14:28 PM

To: Nonresponsive based on revised scope

Subject: Fwd: Unvalidated Electronic Data for Shiloh Church Road, 48708

Attachments: image001.png; ATT00001.htm;

600459.Sample\_Summary\_Report.SHILOH\_CHURCH\_ROAD\_SITE\_Projec.48708.EPW140....pdf; ATT00002.htm; 603400.Sample\_Summary\_Report.SHILOH\_CHURCH\_ROAD\_SITE\_Projec.48708.EPW140....pdf; ATT00003.htm

We will have to check the map w tomorrow

Begin forwarded message:

From: Nonresponsive based on revised scope

Date: February 4, 2020 at 3:58:27 PM EST

To: "Wagner, Christine" < Wagner. Christine@epa.gov>

Subject: RE: Unvalidated Electronic Data for Shiloh Church Road, 48708

Hi Chris,

Attached are the PDF versions for Property 2 results for easier reading.

Still no Dioxin results.

Thank you,

Nonresponsive based on revised scope

From: Nonresponsive based on revised scope

Sent: Tuesday, February 04, 2020 15:54

To: Wagner, Christine < Wagner. Christine@epa.gov>

## Nonresponsive based on revised scope

Subject: Unvalidated Electronic Data for Shiloh Church Road, 48708

\*\* External Email \*\*

Christine,

Attached you will find the unvalidated data for case 48708, SDGs C0B63 & MC0B63 from Shiloh Church Road. Please contact Eric Graybill at (410) 305-2665 or <a href="mailto:graybill.eric@epa.gov">graybill.eric@epa.gov</a> if additional assistance is required.

